



# Dual-Core Intel® Xeon® Processor LV and ULV

## Specification Update

---

*January 2008*

**Notice:** The Dual-Core Intel® Xeon® processor LV or Dual-Core Core Intel® Xeon® processor ULV and Intel® Celeron® processor 1.66 GHz may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are documented in this specification update.



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to Dual-Core Intel® Xeon® processor LV and ULV and Intel® Celeron® Processor 1.66 GHz specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Dual-Core Intel® Xeon® processor LV and ULV and Intel® Celeron® Processor 1.66 GHz may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel® Virtualization Technology requires a computer system with a processor, chipset, BIOS, virtual machine monitor (VMM) and applications enabled for VT. Functionality, performance or other VT benefit will vary depending on hardware and software configurations. VT-enabled BIOS and VMM applications are currently in development.

Intel, Intel Core, Celeron, Pentium, Intel Xeon, Intel SpeedStep and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2005—2008, Intel Corporation. All rights reserved.



# Contents

---

Revision History ..... 4

Preface ..... 6

Summary Tables of Changes ..... 8

Identification Information .....14

Errata .....16

Specification Changes.....42

Specification Clarifications .....43

Documentation Changes .....44

# Revision History

---

Revision	Description	Date
-001	<ul style="list-style-type: none"> <li>Initial Release</li> </ul>	March 2006
-002	<ul style="list-style-type: none"> <li>AF3 – change status to 'Plan Fix'</li> <li>AF4 – Problem, implication, workaround changed.</li> <li>AF9 – Problem statement change, status updated - 'No Fix'</li> <li>AF14 – SDM reference line deleted in problem statement</li> <li>AF28 – Title, problem, implication sections changed (substituted 'retired' with 'executed' and even id to CFH)</li> <li>Added new Errata AF47</li> <li>Added new Errata AF48</li> <li>Added new Errata AF49</li> <li>Added new Errata AF50</li> <li>Added new Errata AF51</li> <li>Added new Errata AF52</li> <li>Added new Errata AF53</li> </ul>	May 2006
-003	<ul style="list-style-type: none"> <li>AF26 – Status changed to – 'No Fix'</li> <li>Added new Errata AF54</li> <li>Added new Errata AF55</li> <li>Added new Errata AF56</li> <li>Added new Errata AF57</li> </ul>	June 2006
-004	<ul style="list-style-type: none"> <li>Updated processor code table</li> <li>AF6 – Updated.</li> <li>AF15 – Workaround updated.</li> <li>AF18 – Updated.</li> <li>AF36 – Updated.</li> <li>AF52 – Updated.</li> <li>Added new Errata AF58</li> <li>Added new Errata AF59</li> <li>Added new Errata AF60</li> <li>Added new Errata AF61</li> </ul>	July 2006
-005	<ul style="list-style-type: none"> <li>Added list of additional processors.</li> <li>Added status column for D0-step processors</li> <li>Added new D0 stepping S-Spec numbers</li> <li>AF4 – All sections updated.</li> </ul>	August 2006

	<ul style="list-style-type: none"> <li>• AF14 – Updated.</li> <li>• AF32 – changed status to 'No Fix'</li> <li>• AF51 – Updated.</li> <li>• Added new Errata AF62, AF63, AF64</li> </ul>	
-006	<ul style="list-style-type: none"> <li>• Updated with ULV product information</li> <li>• Added ULV product SSPEC #.</li> <li>• Added new Errata AF65, AF66, AF67, AF68</li> </ul>	September 2006
-007	<ul style="list-style-type: none"> <li>• Updated Summary Table of Changes (Product prefix table)</li> <li>• Updated names of Software Manuals</li> <li>• AF1 – Updated.</li> <li>• Added new Errata AF69</li> </ul>	October 2006
-008	<ul style="list-style-type: none"> <li>• Updated Summary Table of Changes (Product prefix table)</li> <li>• AF39 – Updated</li> <li>• AF54 – Updated</li> <li>• Added new Errata AF70, AF71, AF72</li> </ul>	November 2006
-009	<ul style="list-style-type: none"> <li>• Updated Summary Table of Changes (Product prefix table)</li> <li>• Added info on Intel® Celeron® Processor 1.66 GHz</li> <li>• AF62 – Removed</li> <li>• AF32 – Updated</li> <li>• AF71 – Updated</li> <li>• Added new Errata AF73, AF74, AF75, AF76, AF77</li> </ul>	December 2006
-010	<ul style="list-style-type: none"> <li>• Updated Summary Table of Changes (Product prefix table)</li> <li>• Added new Errata AF78</li> </ul>	January 2007
-011	<ul style="list-style-type: none"> <li>• Added new Errata AF79</li> </ul>	March 2007
-012	<ul style="list-style-type: none"> <li>• Updated Summary Table of Changes (Product prefix table)</li> <li>• AF16 – Updated</li> <li>• AF49 – Updated</li> <li>• Added new Errata AF80</li> </ul>	October 2007
-013	<ul style="list-style-type: none"> <li>• Updated Summary Table of Changes (Product prefix table)</li> <li>• Added Specification clarification 1</li> <li>• AF33 – updated</li> <li>• AF58 – Updated</li> </ul>	January 2008

§

# Preface

This document is an update to the specifications contained in the following processors:

- Dual-Core Intel® Xeon® Processor LV
- Dual-Core Intel® Xeon® Processor ULV
- Intel® Celeron® Processor 1.66 GHz

This document is an update to the specifications contained in the documents listed in the following Affected Documents/Related Documents table. It is a compilation of device and document errata and specification clarifications and changes, and is intended for hardware system manufacturers and for software developers of applications, operating systems, and tools.

Information types defined in the Nomenclature section of this document are consolidated into this update document and are no longer published in other documents. This document may also contain information that has not been previously published.

## Affected Documents

Document Title	Document Number/Location
<i>Dual-Core Intel® Xeon® Processor LV and ULV Datasheet</i>	<a href="#">311391</a>
<i>Intel® Celeron® Processor 1.66 GHz</i>	<a href="#">315876</a>

## Related Documents

Document Title	Document Number/Location
<i>Embedded Voltage Regulator-Down (EmVRD) 11.0 Design Guidelines for Embedded Implementations Supporting PGA478</i>	<a href="#">311395</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture</i>	<a href="#">253665</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference, A-M</i>	<a href="#">253666</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference, N-Z</i>	<a href="#">253667</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide</i>	<a href="#">253668</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide</i>	<a href="#">253669</a>
<i>Intel® 64 and IA-32 Intel® Architecture Optimization Reference Manual</i>	<a href="#">248966</a>



## Nomenclature

**S-Spec Number** is a five-digit code used to identify products. Products are differentiated by their unique characteristics (e.g., core speed, L2 cache size, package type, etc.) as described in the processor identification information table. Care should be taken to read all notes associated with each S-Spec number

**Errata** are design defects or errors. Errata may cause the Dual-Core Intel® Xeon® processor LV behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

**Note:** Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

§

# Summary Tables of Changes

---

The following table indicates the Specification Changes, Errata, Specification Clarifications or Documentation Changes, which apply to the listed MCH steppings. Intel intends to fix some of the errata in a future stepping of the component, and to account for the other outstanding issues through documentation or Specification Changes as noted. This table uses the following notations:

## Codes Used in Summary Table

### Stepping

X: Erratum, Specification Change or Clarification that applies to this stepping.

(No mark) or (Blank Box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

### Status

Doc: Document change or update that will be implemented.

Plan Fix: This erratum may be fixed in a future stepping of the product.

Fixed: This erratum has been previously fixed.

No Fix: There are no plans to fix this erratum.

Shaded: This item is either new or modified from the previous version of the document.





**Note:** Each Specification Update item is prefixed with a capital letter to distinguish the product. The key below details the letters that are used in Intel's microprocessor Specification Updates:

A =	Dual-Core Intel® Xeon® processor 7000 sequence
C =	Intel® Celeron® processor
D =	Dual-Core Intel® Xeon® processor 2.80 GHz
E =	Intel® Pentium® III processor
F =	Intel® Pentium® processor Extreme Edition and Intel® Pentium® processor
I =	Dual-Core Intel® Xeon® processor 5000 series
J =	64-bit Intel® Xeon® processor MP with 1MB L2 cache
K =	Mobile Intel® Pentium® III processor
L =	Intel® Celeron® D processor
M =	Mobile Intel® Celeron® processor
N =	Intel® Pentium® 4 processor
O =	Intel® Xeon® processor MP
P =	Intel® Xeon® processor
Q =	Mobile Intel® Pentium® 4 processor supporting Hyper-Threading technology on 90-nm process technology
R =	Intel® Pentium® 4 processor on 90 nm process
S =	64-bit Intel® Xeon® processor with 800 MHz system bus (1 MB and 2 MB L2 cache versions)
T =	Mobile Intel® Pentium® 4 processor-M
U =	64-bit Intel® Xeon® processor MP with up to 8MB L3 cache
V =	Mobile Intel® Celeron® processor on .13 micron process in Micro-FCPGA package
W =	Intel® Celeron® M processor
X =	Intel® Pentium® M processor on 90nm process with 2-MB L2 cache and Intel® processor A100 and A110 with 512-KB L2 cache
Y =	Intel® Pentium® M processor
Z =	Mobile Intel® Pentium® 4 processor with 533 MHz system bus
AA =	Intel® Pentium® D processor 900 sequence and Intel® Pentium® processor Extreme Edition 955, 965
AB =	Intel® Pentium® 4 processor 6x1 sequence
AC =	Intel(R) Celeron(R) processor in 478 pin package
AD =	Intel(R) Celeron(R) D processor on 65nm process
AE =	Intel® Core™ Duo processor and Intel® Core™ Solo processor on 65nm process
AF =	Dual-Core Intel® Xeon® processor LV
AG =	Dual-Core Intel® Xeon® processor 5100 series
AH =	Intel® Core™2 Duo/Solo processor for Intel® Centrino® Duo processor technology
AI =	Intel® Core™2 Extreme processor X6800 and Intel® Core™2 Duo desktop processor E6000 and E4000 sequence
AJ =	Quad-Core Intel® Xeon® processor 5300 series
AK =	Intel® Core™2 Extreme quad-core processor QX6000 sequence and Intel® Core™2 Quad processor Q6000 sequence
AL =	Dual-Core Intel® Xeon® processor 7100 series
AM =	Intel® Celeron® processor 400 sequence
AN =	Intel® Pentium® dual-core processor
AO =	Quad-Core Intel® Xeon® processor 3200 series
AP =	Dual-Core Intel® Xeon® processor 3000 series
AQ =	Intel® Pentium® dual-core desktop processor E2000 sequence

AR =	Intel® Celeron® processor 500 series
AS =	Intel® Xeon® processor 7200, 7300 series
AV =	Intel® Core™2 Extreme processor QX9650 and Intel® Core™2 Quad processor Q9000 series
AW =	Intel® Core™ 2 Duo processor E8000 series
AX =	Quad-Core Intel® Xeon® processor 5400 series
AY =	Dual-Core Intel® Xeon® processor 5200 series
AAC =	Intel® Celeron® dual-core processor E1000 series

Δ Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. See [http://www.intel.com/products/processor\\_number](http://www.intel.com/products/processor_number) for details.

Number	Stepping		Plans	ERRATA
	C0	D0		
AF1	X	X	No Fix	FST Instruction with Numeric and Null Segment Exceptions May take Numeric Exception with Incorrect FPU Operand Pointer
AF2	X	X	No Fix	Code Segment Limit Violation May Occur on 4 Gbyte Limit Check
AF3				Errata – Removed.
AF4	X	X	No Fix	REP MOVSB/STOSB Executing with Fast Strings Enabled and Crossing Page Boundaries with Inconsistent Memory Types may use an Incorrect Data Size or Lead to Memory-Ordering Violations
AF5	X	X	No Fix	Memory Aliasing with Inconsistent A and D Bits May Cause Processor Deadlock
AF6	X	X	No Fix	VM Bit is Cleared on Second Fault Handled by Task Switch from Virtual-8086 (VM86)
AF7	X	X	No Fix	Page with PAT (Page Attribute Table) Set to USWC (Uncacheable Speculative Write Combine) While Associated MTRR (Memory Type Range Register) Is UC (Uncacheable) May Consolidate to UC
AF8	X	X	No Fix	FPU Operand Pointer May Not be Cleared Following FINIT/FNINIT
AF9	X	X	No Fix	LTR Instruction May Result in Unexpected Behavior
AF10	X	X	No Fix	Invalid Entries in Page-Directory-Pointer-Table Register (PDPTR) May Cause General Protection (#GP) Exception if the Reserved Bits are Set to One
AF11	X	X	No Fix	VMCALL When Executed during VMX Root Operation while CPL > 0 May Not Generate #GP Fault
AF12	X	X	No Fix	FP Inexact-Result Exception Flag May Not be Set
AF13	X	X	No Fix	A Locked Data Access that Spans Across Two Pages May Cause the System to Hang
AF14	X	X	No Fix	MOV With Debug Register Causes Debug Exception
AF15	X	X	No Fix	INIT Does Not Clear Global Entries in the TLB
AF16	X	X	No Fix	Use of Memory Aliasing with Inconsistent Memory Type May Cause System Hang or a Machine Check Exception

Number	Stepping		Plans	ERRATA
	C0	D0		
AF17	X	X	No Fix	Machine Check Exception May Occur When Interleaving Code between Different Memory Types
AF18	X	X	No Fix	Data Prefetch Performance Monitoring Events Can only be Enabled on a Single Core
AF19	X	X	No Fix	LOCK# Asserted During a Special Cycle Shutdown Transaction May Unexpectedly De-assert
AF20	X	X	No Fix	Disable Execution-Disable Bit (IA32_MISC_ENABLES [34]) is Shared Between Cores
AF21	X	X	No Fix	Last Branch Records (LBR) Updates May be Incorrect After a Task Switch
AF22	X	X	No Fix	Address Reported by Machine-Check Architecture (MCA) on Single-bit L2 ECC Errors May be Incorrect
AF23	X	X	No Fix	Disabling of Single-step On Branch Operation May be Delayed following a POPFD Instruction
AF24	X	X	No Fix	Performance Monitoring Counters that Count External Bus Events May Report Incorrect Values after Processor Power State Transitions
AF25	X	X	No Fix	VERW/VERR/LSL/LAR Instructions May Unexpectedly Update the Last Exception Record (LER) MSR
AF26	X	X	No Fix	General Protection (#GP) Fault May Not Be Signaled On Data Segment Limit Violation Above 4G Limit
AF27	X	X	No Fix	Performance Monitoring Events for Retired Floating Point Operations (C1h) May Not be Accurate
AF28	X	X	No Fix	DR3 Address Match on MOVD/MOVQ/MOVRTQ Memory Store Instruction May Incorrectly Increment Performance Monitoring Count for Saturating SIMD Instructions Retired (Event CFH)
AF29	X	X	No Fix	Global Pages in the Data Translation Look-Aside Buffer (DTLB) May Not be Flushed by RSM instruction before Restoring the Architectural State from SMRAM
AF30	X	X	No Fix	Data Breakpoint/Single Step on MOV SS/POP SS May be Lost after Entry into SMM
AF31	X	X	No Fix	CS Limit Violation on RSM May be Serviced before Higher Priority Interrupts/Exceptions
AF32	X		No Fix	Hardware Prefetch Performance Monitoring Events May be Counted Inaccurately
AF33	X	X	No Fix	Pending x87 FPU Exceptions (#MF) Following STI May Be Serviced Before Higher Priority Interrupts
AF34	X		Plan Fix	CPU_CLK_UNHALTED Performance Monitoring Event (3CH) Counts Clocks when the Processor is in the C1/C2 Processor Power States
AF35	X	X	No Fix	The Processor May Report a #TS Instead of a #GP Fault
AF36	X	X	No Fix	BTS Message May be Lost When the STPCLK# Signal is Active
AF37	X	X	No Fix	Certain Performance Monitoring Counters Related to Bus, L2 Cache and Power Management are Inaccurate
AF38	X	X	No Fix	A Write to an APIC Register Sometimes May Appear to Have Not Occurred
AF39	X	X	No Fix	IO_SMI Indication in SMRAM State Save Area May be Set Incorrectly
AF40	X	X	Plan Fix	IO_SMI Indication in SMRAM State Save Area May be Lost

Number	Stepping		Plans	ERRATA
	C0	D0		
AF41	X	X	No Fix	Logical Processors May Not Detect Write-Back (WB) Memory Writes
AF42	X	X	No Fix	Last Exception Record (LER) MSRs May be Incorrectly Updated
AF43	X	X	No Fix	At a 7:1 Core Frequency to Bus Clock Ratio, the Processor May Livelock when Sending an EOI to MSI Interrupt
AF44	X	X	No Fix	SYSENTER/SYSEXIT Instructions Can Implicitly Load "Null Segment Selector" to SS and CS Registers
AF45	X	X	No Fix	Simultaneous Access to the Same Page Table Entries by both Cores May Lead to Unexpected Processor Behavior
AF46	X	X	No Fix	Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt
AF47	X	X	No Fix	Using 2M/4M Pages When A20M# Is Asserted May Result in Incorrect Address Translations
AF48	X	X	No Fix	Counter Enable bit [22] of IA32_CR_PerfEvtSel0 and IA32_CR_PerfEvtSel1 Do Not Comply with PerfMon (Architectural Performance Monitoring) Specification
AF49	X	X	No Fix	Premature Execution of a Load Operation Prior to Exception Handler Invocation
AF50	X	X	No Fix	Performance Monitoring Events for Retired Instructions (C0H) May Not Be Accurate
AF51	X	X	No Fix	#GP Fault is Not Generated on Writing IA32_MISC_ENABLE[34] When Execute Disable Bit is Not Supported
AF52	X	X	No Fix	Update of Read/Write (R/W) or User/Supervisor (U/S) or Present (P) Bits without TLB Shutdown May Cause Unexpected Processor Behavior
AF53	X	X	No Fix	SSE/SSE2 Streaming Store Resulting in a Self-Modifying Code (SMC) Event May Cause Unexpected Behavior
AF54	X	X	No Fix	Shutdown Condition May Disable Non-Bootstrap Processors
AF55	X	X	No Fix	Split Locked Stores May not Trigger the Monitoring Hardware
AF56	X	X	No Fix	Writing Shared Unaligned Data that Crosses a Cache Line without Proper Semaphores or Barriers May Expose a Memory Ordering Issue
AF57	X	X	No Fix	MSRs Actual Frequency Clock Count (IA32_APERF) or Maximum Frequency Clock Count (IA32_MPERF) May Contain Incorrect Data after a Machine Check Exception (MCE)
AF58	X	X	No Fix	An Enabled Debug Breakpoint or Single Step Trap May Be Taken after MOV SS/POP SS Instruction if it is Followed by an Instruction That Signals a Floating Point Exception
AF59	X	X	No Fix	Incorrect Address Computed For Last Byte of FXSAVE/FXRSTOR Image Leads to Partial Memory Update
AF60	X	X	No Fix	Values for LBR/BTS/BTM will be Incorrect after an Exit from SMM
AF61	X	X	No Fix	Using Memory Type Aliasing with Memory Types WB/WT May Lead to Unpredictable Behavior
AF62				Errata – Removed
AF63	X	X	No Fix	EFLAGS Discrepancy on a Page Fault After a Multiprocessor TLB Shutdown
AF64	X	X	No Fix	Returning to Real Mode from SMM with EFLAGS.VM Set May Result in Unpredictable System Behavior



Number	Stepping		Plans	ERRATA
	C0	D0		
AF65	X	X	No Fix	Performance Monitoring Event FP_ASSIST May Not be Accurate
AF66	X	X	No Fix	The BS Flag in DR6 May be Set for Non-Single-Step #DB Exception
AF67	X	X	No Fix	An Asynchronous MCE During a Far Transfer May Corrupt ESP
AF68	X	X	No Fix	BTM/BTS Branch-From Instruction Address May be Incorrect for Software Interrupts
AF69	X	X	No Fix	Store to WT Memory Data May be Seen in Wrong Order by Two Subsequent Loads
AF70	X	X	No Fix	Single Step Interrupts with Floating Point Exception Pending May Be Mishandled
AF71	X	X	No Fix	Non-Temporal Data Store May be Observed in Wrong Program Order
AF72	X	X	No Fix	Fault on ENTER Instruction May Result in Unexpected Values on Stack Frame
AF73	X	X	No Fix	Unaligned Accesses to Paging Structures May Cause the Processor to Hang
AF74	X	X	No Fix	Microcode Updates Performed During VMX Non-root Operation Could Result in Unexpected Behavior
AF75	X	X	No Fix	INVLPG Operation for Large (2M/4M) Pages may be Incomplete under Certain Conditions
AF76	X	X	No Fix	Page Access Bit May be Set Prior to Signaling a Code Segment Limit Fault
AF77	X	X	No Fix	Performance Monitoring Events for Hardware Prefetch Requests (4EH) and Hardware Prefetch Request Cache Misses (4FH) May Not be Accurate
AF78	X	X	No Fix	EFLAGS, CR0, CR4 and the EXF4 Signal May be Incorrect after Shutdown
AF79	X	X	No Fix	Store Ordering May be Incorrect between WC and WP Memory Types
AF80	X	X	No Fix	A WB Store Following a REP STOS/MOVS or FXSAVE May Lead to Memory-Ordering Violations

Number	SPECIFICATION CHANGES
	There are no Specification Changes in this Specification Update revision.

Number	SPECIFICATION CLARIFICATIONS
	There are no Specification Clarifications in this Specification Update revision.

Number	DOCUMENTATION CHANGES
	There are no Documentation Changes in this Specification Update revision.

§

# Identification Information

## Component Identification via Programming Interface

The processor stepping can be identified by the following register contents:

Family <sup>1</sup>	Model <sup>2</sup>
0110	1110


### NOTES:

1. The family corresponds to bit [11:8] of the EDX register after RESET, bits [11:8] of the EAX register after the CUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
2. The family corresponds to bit [7:4] of the EDX register after RESET, bits [7:4] of the EAX register after the CUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX, and EDX registers after the CUID instruction is executed with a 2 in the EAX register. Refer to the *Intel Processor Identification and the CUID Instruction Application Note* (AP-485) for further information on the CUID instruction.

## Component Marking Information

Figure 1. Processor (Micro-FCPGA) S-Spec Markings





**Table 1. Processor Identification Information**

S-SPEC#	FSB Speed	Package	Stepping	CPUID	Speed HFM/LFM (GHz)	VID HFM/LFM (Volts)
SL9HS	667 MHz	Micro-FCPGA	D-0	06ECh	1.66/1.00	1.0-1.2125/ 0.825 – 1.1 <sup>1</sup> ( <b>ULV</b> )
SL9HP	667 MHz	Micro-FCPGA	D-0	06ECh	1.66/1.00	1.1125-1.275/ 0.825 – 1.1 <sup>1</sup> ( <b>LV</b> )
SL9HN	667 MHz	Micro-FCPGA	D-0	06ECh	2.00/1.00	1.1125-1.275/ 0.825 – 1.1 <sup>1</sup> ( <b>LV</b> )
SL9S3	667 MHz	Micro-FCPGA	D-0	06ECh	1.66/1.00	1.1125-1.275/ 0.825 – 1.1 <sup>1</sup> ( <b>ICP</b> )
SL98Q	667 MHz	Micro-FCPGA	C-0	06E8h	1.66/1.00	1.1125 – 1.2/ 0.825 – 1.1 <sup>1</sup>
SL8WT	667 MHz	Micro-FCPGA	C-0	06E8h	2.00/1.00	1.1125 – 1.2/ 0.825 – 1.1 <sup>1</sup>

**NOTES:** (1) Optimized VID (OVID) range. Individual processor VID values may be calibrated during manufacturing such that two devices at the same speed may have different VID settings.

# Errata

---

## AF1. FST Instruction with Numeric and Null Segment Exceptions May take Numeric Exception with Incorrect FPU Operand Pointer

**Problem:** If execution of an FST (Store Floating Point Value) instruction would generate both numeric and null segment exceptions, the numeric exception may be taken first and with the Null x87 FPU Instruction Operand (Data) Pointer.

**Implication:** Due to this erratum, on an FST instruction the processor reports a numeric exception instead of reporting an exception because of a Null segment. If the numeric exception handler tries to access the FST data it will get a #GP fault. Intel has not observed this erratum with any commercially available software, or system.

**Workaround:** The numeric exception handler should check the segment and if it is Null avoid further access to the data that caused the fault.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## AF2. Code Segment Limit Violation May Occur on 4 Gbyte Limit Check

**Problem:** Code Segment limit violation may occur on 4 Gbyte limit check when the code stream wraps around in a way that one instruction ends at the last byte of the segment and the next instruction begins at 0x0.

**Implication:** This is a rare condition that may result in a system hang. Intel has not observed this erratum with any commercially available software, or system.

**Workaround:** Avoid code that wraps around segment limit.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## AF3. POPF and POPFD Instructions That Set the Trap Flag Bit May Cause Unpredictable Processor Behavior

**Problem:** In some rare cases, POPF and POPFD instructions that set the Trap Flag (TF) bit in the EFLAGS register (causing the processor to enter Single-Step mode) may cause unpredictable processor behavior.

**Implication:** Single-Step operation is typically enabled during software debug activities, not during normal system operation.

**Workaround:** There is no workaround for Single-Step operation in commercially available software. For debug activities on custom software the POPF and POPFD instructions could be immediately followed by a NOP instruction to facilitate correct execution.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).





**AF4. REP MOVS/STOS Executing with Fast Strings Enabled and Crossing Page Boundaries with Inconsistent Memory Types may use an Incorrect Data Size or Lead to Memory-Ordering Violation**

**Problem:** Under certain conditions as described in the Software Developers Manual section “Out-of-Order Stores For String Operations in Pentium 4, Intel Xeon, and P6 Family Processors” the processor performs REP MOVS or REP STOS as fast strings. Due to this erratum fast string REP MOVS/REP STOS instructions that cross page boundaries from WB/WC memory types to UC/WP/WT memory types, may start using an incorrect data size or may observe memory ordering violations.

**Implication:** Upon crossing the page boundary the following may occur, dependent on the new page memory type:

- UC the data size of each write will now always be 8 bytes, as opposed to the original data size.
- WP the data size of each write will now always be 8 bytes, as opposed to the original data size and there may be a memory ordering violation.
- WT there may be a memory ordering violation.

**Workaround:** Software should avoid crossing page boundaries from WB or WC memory type to UC, WP or WT memory type within a single REP MOVS or REP STOS instruction that will execute with fast strings enabled.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF5. Memory Aliasing with Inconsistent A and D Bits May Cause Processor Deadlock**

**Problem:** In the event that software implements memory aliasing by having two Page Directory Entries (PDEs) point to a common Page Table Entry (PTE) and the Accessed and Dirty bits for the two PDEs are allowed to become inconsistent the processor may become deadlocked.

**Implication:** This erratum has not been observed with commercially available software.

**Workaround:** Software that needs to implement memory aliasing in this way should manage the consistency of the Accessed and Dirty bits.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF6. VM Bit is Cleared on Second Fault Handled by Task Switch from Virtual-8086 (VM86)**

**Problem:** Following a task switch to any fault handler that was initiated while the processor was in VM86 mode, if there is an additional fault while servicing the original task switch then the VM bit will be incorrectly cleared in EFLAGS, data segments will not be pushed and the processor will not return to the correct mode upon completion of the second fault handler via IRET.

**Implication:** When the OS recovers from the second fault handler, the processor will no longer be in VM86 mode. Normally, operating systems should prevent interrupt task switches from faulting, thus the scenario should not occur under normal circumstances.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF7. Page with PAT (Page Attribute Table) Set to USWC (Uncacheable Speculative Write Combine) While Associated MTRR (Memory Type Range Register) Is UC (Uncacheable) May Consolidate to UC**

**Problem:** A page whose PAT memory type is USWC while the relevant MTRR memory type is UC, the consolidated memory type may be treated as UC (rather than WC as specified in *IA-32 Intel® Architecture Software Developer's Manual*).

**Implication:** When this erratum occurs, the memory page may be as UC (rather than WC). This may have a negative performance impact.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF8. FPU Operand Pointer May Not be Cleared Following FINIT/FNINIT**

**Problem:** Initializing the floating point state with either FINIT or FNINIT, may not clear the x87 FPU Operand (Data) Pointer Offset and the x87 FPU Operand (Data) Pointer Selector (both fields form the FPUDataPointer). Saving the floating point environment with FSTENV, FNSTENV, or floating point state with FSAVE, FNSAVE or FXSAVE before an intervening FP instruction may save uninitialized values for the FPUDataPointer.

**Implication:** When this erratum occurs, the values for FPUDataPointer in the saved floating point image or floating point environment structure may appear to be random values. Executing any non-control FP instruction with memory operand will initialize the FPUDataPointer. Intel has not observed this erratum with any commercially available software.

**Workaround:** After initialization, do not expect the FPUDataPointer in a floating point state or floating point environment saved memory image to be correct, until at least one non-control FP instruction with a memory operand has been executed.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF9. LTR Instruction May Result in Unexpected Behavior**

**Problem:** Under certain circumstances an LTR (Load Task Register) instruction may result in an unexpected behavior if all the following conditions are met:

1. Invalid data selector of the TR (Task Register) resulting with either #GP (General Protection Fault) or #NP (Segment Not Present Fault).
2. GDT (Global Descriptor Table) is not 8-bytes aligned.

**Implication:** If all conditions have been met then under certain circumstances LTR instruction may result in system hang, memory corruption or other unexpected behavior. This erratum has not been observed in commercial operating systems or software.

**Workaround:** Operating system software should align GDT to 8-bytes, as recommended in the Software Developer's Manual section "Segment Descriptor Tables". For performance reasons, GDT is typically aligned to 8-bytes.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



**AF10. Invalid Entries in Page-Directory-Pointer-Table Register (PDPTR) May Cause General Protection (#GP) Exception If the Reserved Bits Are Set to One**

**Problem:** Invalid entries in the Page-Directory-Pointer-Table Register (PDPTR) that have the reserved bits set to one may cause a General Protection (#GP) exception.

**Implication:** Intel has not observed this erratum with any commercially available software.

**Workaround:** Do not set the reserved bits to one when PDPTR entries are invalid.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## AF11. VMCALL When Executed during VMX Root Operation while CPL > 0 May Not Generate #GP Fault

**Problem:** If VMCALL is executed during VMX root operation with CPL > 0, the expected behavior is for the processor to generate a General Protection Fault (#GP). Due to this erratum, the #GP fault may not be generated.

**Implication:** VM Monitor code running with CPL > 0 may not generate #GP fault on VMCALL, but still will behave as if VM Exit had occurred.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## AF12. FP Inexact-Result Exception Flag May Not be Set

**Problem:** When the result of a floating-point operation is not exactly representable in the destination format (1/3 in binary form, for example), an inexact-result (precision) exception occurs. When this occurs, the PE bit (bit 5 of the FPU status word) is normally set by the processor. Under certain rare conditions, this bit may not be set when this rounding occurs. However, other actions taken by the processor (invoking the software exception handler if the exception is unmasked) are not affected. This erratum can only occur if the floating-point operation which causes the precision exception is immediately followed by one of the following instructions:

- FST m32real
- FST m64real
- FSTP m32real
- FSTP m64real
- FSTP m80real
- FIST m16int
- FIST m32int
- FISTP m16int
- FISTP m32int
- FISTP m64int

Note that even if this combination of instructions is encountered, there is also a dependency on the internal pipelining and execution state of both instructions in the processor.

**Implication:** Inexact-result exceptions are commonly masked or ignored by applications, as it happens frequently, and produces a rounded result acceptable to most applications. The PE bit of the FPU status word may not always be set upon receiving an inexact-result exception. Thus, if these exceptions are unmasked, a floating-point error exception handler may not recognize that a precision exception occurred. Note that this is a “sticky” bit, i.e., once set by an inexact-result condition, it remains set until cleared by software.

**Workaround:** This condition can be avoided by inserting two non-floating-point instructions between the two floating-point instructions.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



**AF13. A Locked Data Access that Spans Across Two Pages May Cause the System to Hang**

**Problem:** An instruction with lock data access that spans across two pages may, given some rare internal conditions, hang the system.

**Implication:** When this erratum occurs, the system may hang. Intel has not observed this erratum with any commercially available software or system.

**Workaround:** A locked data access should always be aligned.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF14. MOV To/From Debug Registers Causes Debug Exception**

**Problem:** When in V86 mode, if a MOV instruction is executed to/from a debug register, a general-protection exception (#GP) should be generated. However, in the case when the general detect enable flag (GD) bit is set, the observed behavior is that a debug exception (#DB) is generated instead.

**Implication:** With debug-register protection enabled (i.e., the GD bit set), when attempting to execute a MOV on debug registers in V86 mode, a debug exception will be generated instead of the expected general-protection fault.

**Workaround:** In general, operating systems do not set the GD bit when they are in V86 mode. The GD bit is generally set and used by debuggers. The debug exception handler should check that the exception did not occur in V86 mode before continuing. If the exception did occur in V86 mode, the exception may be directed to the general-protection exception handler.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF15. INIT Does Not Clear Global Entries in the TLB**

**Problem:** INIT may not flush a TLB entry when:

1. The processor is in protected mode with paging enabled and the page global enable flag is set (PGE bit of CR4 register)
2. G bit for the page table entry is set
3. TLB entry is present in TLB when INIT occurs.

**Implication:** Software may encounter unexpected page fault or incorrect address translation due to a TLB entry erroneously left in TLB after INIT.

**Workaround:** Write to CR3, CR4 (setting bits PSE, PGE or PAE) or CR0 (setting bits PG or PE) registers before writing to memory early in BIOS code to clear all the global entries from TLB.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF16. Use of Memory Aliasing with Inconsistent Memory Type May Cause System Hang or a Machine Check Exception**

**Problem:** Software that implements memory aliasing by having more than one linear addresses mapped to the same physical page with different cache types may cause the system to hang or to report a machine check exception (MCE). This would occur if one of the addresses is non-cacheable used in code segment and the other a cacheable address. If the cacheable address finds its way in instruction cache, and non-cacheable address is fetched in IFU, the processor may invalidate the non-cacheable address from the fetch unit. Any micro-architectural event that causes instruction restart will expect this instruction to still be in fetch unit and lack of it will cause a system hang or an MCE.

**Implication:** This erratum has not been observed with commercially available software.

**Workaround:** Although it is possible to have a single physical page mapped by two different linear addresses with different memory types, Intel has strongly discouraged this practice as it may lead to undefined results. Software that needs to implement memory aliasing should manage the memory type consistency.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF17. Machine Check Exception May Occur When Interleaving Code between Different Memory Types**

**Problem:** A small window of opportunity exists where code fetches interleaved between different memory types may cause a machine check exception. A complex set of micro-architectural boundary conditions is required to expose this window.

**Implication:** Interleaved instruction fetches between different memory types may result in a machine check exception. The system may hang if machine check exceptions are disabled. Intel has not observed the occurrence of this erratum while running commercially available applications or operating systems.

**Workaround:** Software can avoid this erratum by placing a serializing instruction between code fetches between different memory types.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF18. Data Prefetch Performance Monitoring Events Can Only be Enabled on a Single Core**

**Problem:** Current implementation of Data Prefetch performance monitoring events allow counting only for a single core at a time.

**Implication:** Dual-core support for counting Data Prefetch performance monitoring events is not currently available.

**Workaround:** Software should enable Data Prefetch performance monitoring events on one core at a time.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



**AF19. LOCK# Asserted During a Special Cycle Shutdown Transaction May Unexpectedly De-assert**

**Problem:** During a processor shutdown transaction, when LOCK# is asserted and if a DEFER# is received during a snoop phase and the Locked transaction is pipelined on the front side bus (FSB), LOCK# may unexpectedly de-assert.

**Implication:** When this erratum occurs, the system may hang during shutdown. Intel has not observed this erratum with any commercially available systems or software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF20. Disable Execution-Disable Bit (IA32\_MISC\_ENABLES [34]) Is Shared between Cores**

**Problem:** The bit 34 of the IA32\_MISC\_ENABLES Model Specific Register (MSR) is shared between the execution cores.

**Implication:** Both cores will operate according to the shared value of bit IA32\_MISC\_ENABLES [34].

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF21. Last Branch Records (LBR) Updates May be Incorrect after a Task Switch**

**Problem:** A Task-State Segment (TSS) task switch may incorrectly set the LBR\_FROM value to the LBR\_TO value.

**Implication:** The LBR\_FROM will have the incorrect address of the Branch Instruction.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF22. Address Reported by Machine-Check Architecture (MCA) on Single-bit L2 ECC Errors May be Incorrect**

**Problem:** When correctable single-bit ECC errors occur in the L2 cache the address is logged in the MCA address register (MCi\_ADDR). Under some scenarios, the address reported may be incorrect.

**Implication:** Software should not rely on the value reported in MCi\_ADDR, for Single-bit L2 ECC errors

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF23. Disabling of Single-step On Branch Operation May be Delayed following a POPFD Instruction**

**Problem:** Disabling of Single-step On Branch Operation may be delayed, if the following conditions are met:

1. “Single Step On Branch Mode” is enabled (DebugCtlMSR.BTF and EFLAGS.TF are set)
2. POPFD used to clear EFLAGS.TF
3. A jump instruction (JMP, Jcc, etc.) is executed immediately after POPFD

**Implication:** Single-step On Branch mode may remain in effect for one instruction after the POPFD instruction disables it by clearing the EFLAGS.TF bit.

**Workaround:** There is no workaround for Single-Step operation in commercially available software. The workaround for custom software is to execute at least one instruction following POPFD before issuing a JMP instruction.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF24. Performance Monitoring Counters That Count External Bus Events May Report Incorrect Values after Processor Power State Transitions**

**Problem:** Performance monitoring counters that count external bus events operate when the processor is in the Active state (C0). If a processor transitions to a new power state, these Performance monitoring counters will stop counting, even if the event being counted remains active.

**Implication:** After transitioning between processor power states, software may observe incorrect counts in Performance monitoring counters that count external bus events.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF25. VERW/VERR/LSL/LAR Instructions May Unexpectedly Update the Last Exception Record (LER) MSR**

**Problem:** The LER MSR may be unexpectedly updated, if the resultant value of the Zero Flag (ZF) is zero after executing the following instructions:

1. VERR (ZF=0 indicates unsuccessful segment read verification)
2. VERW (ZF=0 indicates unsuccessful segment write verification)
3. LAR (ZF=0 indicates unsuccessful access rights load)
4. LSL (ZF=0 indicates unsuccessful segment limit load)

**Implication:** The value of the LER MSR may be inaccurate if VERW/VERR/LSL/LAR instructions are executed after the occurrence of an exception.

**Workaround:** Software exception handlers that rely on the LER MSR value should read the LER MSR before executing VERW/VERR/LSL/LAR instructions.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).





**AF26. General Protection (#GP) Fault May Not Be Signaled on Data Segment Limit Violation above 4-G Limit**

**Problem:** Memory accesses to flat data segments (base = 00000000h) that occur above the 4G limit (0xffffffffh) may not signal a #GP fault.

**Implication:** When such memory accesses occur, the system may not issue a #GP fault.

**Workaround:** Software should ensure that memory accesses do not occur above the 4G limit (0xffffffffh).

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF27. Performance Monitoring Events for Retired Floating Point Operations (C1h) May Not Be Accurate**

**Problem:** Performance monitoring events that count retired floating point operations may be too high.

**Implication:** The Performance Monitoring Event may have an inaccurate count.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#)

**AF28. DR3 Address Match on MOVD/MOVB/MOVBQ Memory Store Instruction May Incorrectly Increment Performance Monitoring Count for Saturating SIMD Instructions Retired (Event CFH)**

**Problem:** Performance monitoring for Event CFH normally increments on saturating SIMD instruction retired. Regardless of DR7 programming, if the linear address of a retiring memory store MOVD/MOVB/MOVBQ instruction executed matches the address in DR3, the CFH counter may be incorrectly incremented.

**Implication:** The value observed for performance monitoring count for saturating SIMD instructions retired may be too high. The size of the error is dependent on the number of occurrences of the conditions described above, while the counter is active.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF29. Global Pages in the Data Translation Look-Aside Buffer (DTLB) May Not be Flushed by RSM instruction before Restoring the Architectural State from SMRAM**

**Problem:** The Resume from System Management Mode (RSM) instruction does not flush global pages from the Data Translation Look-Aside Buffer (DTLB) prior to reloading the saved architectural state.

**Implication:** If SMM turns on paging with global paging enabled and then maps any of linear addresses of SMRAM using global pages, RSM may load data from the wrong location.

**Workaround:** Do not use global pages in System Management Mode.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF30. Data Breakpoint/Single Step on MOV SS/POP SS May Be Lost after Entry into SMM**

**Problem:** Data Breakpoint/Single Step exceptions are normally blocked for one instruction following MOV SS/POP SS instructions. Immediately after executing these instructions, if the processor enters SMM (System Management Mode), upon RSM (resume from SMM) operation, normal processing of Data Breakpoint/Single Step exceptions is restored.

Because of this erratum, Data Breakpoints/Single step exceptions on MOVSS/POPSS instructions may be lost under one of the following conditions.

1. Following SMM entry and after RSM, the next instruction to be executed is HLT or MWAIT
2. SMM entry after executing MOV SS/POP SS is the result of executing an I/O instruction that triggers a synchronous SMI (System Management Interrupt).

**Implication:** Data Breakpoints/Single step operation on MOV SS/POP SS instructions may be unreliable in the presence of SMIs.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



**AF31. CS Limit Violation on RSM May Be Serviced before Higher Priority Interrupts/Exceptions**

**Problem:** When the processor encounters a CS (Code Segment) limit violation, a #GP (General Protection Exception) fault is generated after all higher priority Interrupts and exceptions are serviced. Because of this erratum, if RSM (Resume from System Management Mode) returns to execution flow where a CS limit violation occurs, the #GP fault may be serviced before a higher priority Interrupt or Exception (e.g. NMI (Non-Maskable Interrupt), Debug break(#DB), Machine Check (#MC), etc).

**Implication:** Operating systems may observe a #GP fault being serviced before higher priority interrupts and Exceptions.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF32. Hardware Prefetch Performance Monitoring Events May Be Counted Inaccurately**

**Problem:** Hardware prefetch activity is not accurately reflected in the hardware prefetch performance monitoring.

**Implication:** This erratum may cause inaccurate counting for all hardware prefetch performance monitoring events.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF33. Pending x87 FPU Exceptions (#MF) Following STI May Be Serviced before Higher Priority Interrupts**

**Problem:** Interrupts that are pending prior to the execution of the STI (Set Interrupt Flag) instruction are normally serviced immediately after the instruction following the STI. An exception to this is if the following instruction triggers a #MF. In this situation, the interrupt should be serviced before the #MF. Because of this erratum, if following STI, an instruction that triggers a #MF is executed while STPCLK#, Enhanced Intel SpeedStep® Technology transitions or Thermal Monitor 1 events occur, the pending #MF may be serviced before higher priority interrupts.

**Implication:** Software may observe #MF being serviced before higher priority interrupts.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF34. CPU\_CLK\_UNHALTED Performance Monitoring Event (3CH) Counts Clocks when the Processor is in the C1/C2 Processor Power States**

**Problem:** The CPU\_CLK\_UNHALTED performance monitoring event should only count clocks when the processor is running. However, due to this erratum, CPU\_CLK\_UNHALTED performance monitoring event may count clocks when the cores have been halted in the C1/C2 processor power states. The count may be incorrect when the two cores are not in C1/C2 state simultaneously

**Implication:** The CPU\_CLK\_UNHALTED performance monitoring event may read a somewhat larger value than expected.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **AF35. The Processor May Report a #TS Instead of a #GP Fault**

**Problem:** A jump to a busy TSS (Task-State Segment) may cause a #TS (invalid TSS exception) instead of a #GP fault (general protection exception).

**Implication:** Operation systems that access a busy TSS may get invalid TSS fault instead of a #GP fault. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **AF36. BTS Message May Be Lost When the STPCLK# Signal is Active**

**Problem:** STPCLK# is asserted to enable the processor to enter a low-power state. Under some circumstances, when STPCLK# becomes active, a pending BTS (Branch Trace Store) message may be either lost and not written or written with corrupted branch address to the Debug Store area.

**Implication:** BTS messages may be lost in the presence of STPCLK# assertions.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **AF37. Certain Performance Monitoring Counters Related to Bus, L2 Cache and Power Management are Inaccurate**

**Problem:** All Performance Monitoring Counters in the ranges 21H-3DH and 60H-7FH may have inaccurate results up to +/- 7.

**Implication:** There may be a small error in the affected counts.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **AF38. A Write to an APIC Register Sometimes May Appear to Have Not Occurred**

**Problem:** With respect to the retirement of instructions, stores to the uncacheable memory-based APIC register space are handled in a non-synchronized way. For example if an instruction that masks the interrupt flag, e.g. CLI, is executed soon after an uncacheable write to the Task Priority Register (TPR) that lowers the APIC priority, the interrupt masking operation may take effect before the actual priority has been lowered. This may cause interrupts whose priority is lower than the initial TPR, but higher than the final TPR, to not be serviced until the interrupt enabled flag is finally set, i.e. by STI instruction. Interrupts will remain pending and are not lost.

**Implication:** In this example the processor may allow interrupts to be accepted but may delay their service.

**Workaround:** This non-synchronization can be avoided by issuing an APIC register read after the APIC register write. This will force the store to the APIC register before any subsequent instructions are executed. No commercial operating system is known to be impacted by this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



#### **AF39. IO\_SMI Indication in SMRAM State Save Area May Be Set Incorrectly**

**Problem:** The IO\_SMI bit in SMRAM's location 7FA4H is set to "1" by the CPU to indicate a System Management Interrupt (SMI) occurred as the result of executing an instruction that reads from an I/O port. Due to this erratum, the IO\_SMI bit may be incorrectly set by:

- A non-I/O instruction
- SMI is pending while a lower priority event interrupts
- A REP I/O read
- An I/O read that redirects to MWAIT
- In systems supporting Intel® Virtualization Technology a fault in the middle of an IO operation that causes a VM Exit

**Implication:** SMM handlers may get false IO\_SMI indication.

**Workaround:** The SMM handler has to evaluate the saved context to determine if the SMI was triggered by an instruction that read from an I/O port. The SMM handler must not restart an I/O instruction if the platform has not been configured to generate a synchronous SMI for the recorded I/O port address.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF40. IO\_SMI Indication in SMRAM State Save Area May Be Lost**

**Problem:** The IO\_SMI bit in SMRAM's location 7FA4H is set to "1" by the CPU to indicate a System Management Interrupt (SMI) that occurred as the result of executing an instruction that read from an I/O port. Due to this erratum, the setting of the IO\_SMI bit may be lost. This may happen if following the instruction that read from an I/O port, there is an instruction with a memory operand that results in one of the following:

- Update of a Page Table Entry (PTE) Accessed (A) or Dirty (D) bits.
- Page Fault (#PF)
- A REP I/O read
- Unaligned Memory access where either address of the first or last byte of the access (ex: (Address1stByte AND NOT 0x3F) OR (AddressLastByte AND NOT 0x3F) ) is equal to the address in one of the Debug Address Registers (DR0-DR3) (ex. DRx AND NOT 0x3F ) as long as any address breakpoint is enabled through the Debug Control Register (DR7).

**Implication:** SMI handlers may not be able to identify the occurrence of I/O SMIs.

**Workaround:** It is possible for BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF41. Logical Processors May Not Detect Write-Back (WB) Memory Writes**

**Problem:** Multiprocessor systems may use polling of memory semaphores to synchronize software activity. Because of this erratum, if a logical processor is polling a WB memory location while it is being updated by another logical processor, the update may not be detected.

**Implication:** System may livelock due to polling loop and undetected semaphore change. Intel has not observed this erratum on commercially available systems.

**Workaround:** It is possible for BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF42. Last Exception Record (LER) MSRs May be Incorrectly Updated**

**Problem:** The LASTINTTOIP and LASTINTFROMIP MSRs (1DDH-1DEH) may contain incorrect values after the following events: masked SSE2 floating-point exception, StopClk, NMI and INT.

**Implication:** The value of the LER MSR may be incorrectly updated to point to a SIMD Floating-Point instruction even though no exception occurred on that instruction or to point to an instruction that was preceded by a StopClk interrupt or rarely not to be updated on Interrupts (NMI and INT).

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF43. At a 7:1 Core Frequency to Bus Clock Ratio, the Processor May Livelock when Sending an EOI to MSI Interrupt**

**Problem:** The CPU may encounter a livelock when sending EOI to MSI level interrupt due to multiple retry requests from MCH at 7:1 core frequency to bus clock ratio.

**Implication:** The system will enter a livelock condition (hang).

**Workaround:** None. The Dual-Core Intel® Xeon® processor LV will not support a 7:1 core frequency to bus clock ratio.

**Status:** For the affected steppings, see the [Summary Tables of Changes](#).

#### **AF44. SYSENTER/SYSEXIT Instructions Can Implicitly Load “Null Segment Selector” to SS and CS Registers**

**Problem:** According to the processor specification, attempting to load a null segment selector into the CS and SS segment registers should generate a General Protection Fault (#GP). Although loading a null segment selector to the other segment registers is allowed, the processor will generate an exception when the segment register holding a null selector is used to access memory. However, the SYSENTER instruction can implicitly load a null value to the SS segment selector. This can occur if the value in SYSENTER\_CS\_MSR is between FFF8h and FFFBh when the SYSENTER instruction is executed. This behavior is part of the SYSENTER/SYSEXIT instruction definition; the content of the SYSTEM\_CS\_MSR is always incremented by 8 before it is loaded into the SS. This operation will set the null bit in the segment selector if a null result is generated, but it does not generate a #GP on the SYSENTER instruction itself. An exception will be generated as expected when the SS register is used to access memory, however. The SYSEXIT instruction will also exhibit this behavior for both CS and SS when executed with the value in SYSENTER\_CS\_MSR between FFF0h and FFF3h, or between FFE8h and FFEb, inclusive.

**Implication:** These instructions are intended for operating system use. If this erratum occurs (and the OS does not ensure that the processor never has a null segment selector in the SS or CS segment registers), the processor's behavior may become unpredictable, possibly resulting in system failure.

**Workaround:** Do not initialize the SYSTEM\_CS\_MSR with the values between FFF8h and FFFBh, FFF0h and FFF3h, or FFE8h and FFEb before executing SYSENTER or SYSEXIT.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF45. Simultaneous Access to the Same Page Translation Entries by Both Cores May Lead to Unexpected Processor Behavior**

**Problem:** When the following conditions occur simultaneously, this may create a rare internal condition which may lead to unexpected processor behavior.

- One core is updating a page table entry, including the processor setting the Accessed and/or Dirty bits in the PTE as the result of an access
- The other core is using the same translation entry

**Implication:** Unpredictable behavior in the processor may lead to livelock and shutdown. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF46. Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt**

**Problem:** If a local interrupt is pending when the LVT entry is written, an interrupt may be taken on the new interrupt vector even if the mask bit is set.

**Implication:** An interrupt may immediately be generated with the new vector when a LVT entry is written, even if the new LVT entry has the mask bit set. If there is no Interrupt Service Routine (ISR) set up for that vector the system will GP fault. If the ISR does not do an End of Interrupt (EOI) the bit for the vector will be left set in the in-service register and mask all interrupts at the same or lower priority.

**Workaround:** Any vector programmed into an LVT entry must have an ISR associated with it, even if that vector was programmed as masked. This ISR routine must do an EOI to clear any unexpected interrupts that may occur. The ISR associated with the spurious vector does not generate an EOI, therefore the spurious vector should not be used when writing the LVT.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF47. Using 2M/4M Pages When A20M# Is Asserted May Result in Incorrect Address Translations**

**Problem:** An external A20M# pin if enabled forces address bit 20 to be masked (forced to zero) to emulate real-address mode address wraparound at 1 megabyte. However, if all of the following conditions are met, address bit 20 may not be masked.

- paging is enabled
- a linear address has bit 20 set
- the address references a large page
- A20M# is enabled

**Implication:** When A20M# is enabled and an address references a large page the resulting translated physical address may be incorrect. This erratum has not been observed with any commercially available operating system.

**Workaround:** Operating systems should not allow A20M# to be enabled if the masking of address bit 20 could be applied to an address that references a large page. A20M# is normally only used with the first megabyte of memory.



**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF48. Counter Enable bit [22] of IA32\_CR\_PerfEvtSel0 and IA32\_CR\_PerfEvtSel1 Do Not Comply with PerfMon (Architectural Performance Monitoring) Specification**

**Problem:** According to the Architectural Performance Monitoring specification the two PerfMon counters can be disabled/enabled through the corresponding Counter Enable bit [22] of IA32\_CR\_PerfEvtSel0/1. Due to this erratum the following occurs:

1. bit [22] of IA32\_CR\_PerfEvtSel0 enables/disables both counters
2. bit [22] of IA32\_CR\_PerfEvtSel1 doesn't function

**Implication:** Software cannot enable/disable only one of the two PerfMon counters through the corresponding Counter Enable bit [22] of IA32\_CR\_PerfEvtSel0/1.

**Workaround:** Software should enable/disable both PerfMon counters together through Counter Enable bit [22] of IA32\_CR\_PerfEvtSel0 only. Alternatively, Software can effectively disable any one of the counters by clearing both Krnl and App bits [17:16] in the corresponding IA32\_CR\_PerfEvtSel0/1.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#)

#### **AF49. Prior Premature Execution of a Load Operation to Exception Handler Invocation**

**Problem:** If any of the below circumstances occur it is possible that the load portion of the instruction will have executed before the exception handler is entered.

- If an instruction that performs a memory load causes a code segment limit violation.
- If a waiting X87 floating-point (FP) instruction or MMX™ technology (MMX) instruction that performs a memory load has a floating-point exception pending.
- If an MMX or SSE/SSE2/SSE3/SSSE3 extensions (SSE) instruction that performs a memory load and has either CR0.EM=1 (Emulation bit set), or a floating-point Top-of-Stack (FP TOS) not equal to 0, or a DNA exception pending.

**Implication:** In normal code execution where the target of the load operation is to write back memory there is no impact from the load being prematurely executed, or from the restart and subsequent re-execution of that instruction by the exception handler. If the target of the load is to uncached memory that has a system side-effect, restarting the instruction may cause unexpected system behavior due to the repetition of the side-effect. Particularly, while CR0.TS [bit 3] is set, a MOVD/MOVQ with MMX/XMM register operands may issue a memory load before getting the DNA exception.

**Workaround:** Code which performs loads from memory that has side-effects can effectively workaround this behavior by using simple integer-based load instructions when accessing side-effect memory and by ensuring that all code is written such that a code segment limit violation cannot occur as a part of reading from side-effect memory.

**Status:** For the affected steppings, see the [Summary Tables of Changes](#)

#### **AF50. Performance Monitoring Events for Retired Instructions (C0H) May Not Be Accurate**

**Problem:** The INST\_RETIRED performance monitor may miscount retired instructions as follows:

- Repeat string and repeat I/O operations are not counted when a hardware interrupt is received during





or after the last iteration of the repeat flow.

- VMLAUNCH and VMRESUME instructions are not counted.
- HLT and MWAIT instructions are not counted. The following instructions, if executed during HLT or MWAIT events, are also not counted:
  - a) RSM from a C-state SMI during an MWAIT instruction.
  - b) RSM from an SMI during a HLT instruction.

**Implication:** There may be a smaller than expected value in the INST\_RETIRED performance monitoring counter. The extent to which this value is smaller than expected is determined by the frequency of the above cases.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#)

#### **AF51. #GP Fault is Not Generated on Writing IA32\_MISC\_ENABLE [34] When Execute Disable Bit is Not Supported**

**Problem:** A #GP fault is not generated on writing to IA32\_MISC\_ENABLE [34] bit in a processor which does not support Execute Disable Bit functionality.

**Implication:** Writing to IA32\_MISC\_ENABLE [34] bit is silently ignored without generating a fault.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF52. Update of Read/Write (R/W) or User/Supervisor (U/S) or Present (P) Bits without TLB Shutdown May Cause Unexpected Processor Behavior**

**Problem:** Updating a page table entry by changing R/W, U/S or P bits without TLB shutdown (as defined by the 4 step procedure in "Propagation of Page Table and Page Directory Entry Changes to Multiple Processors" In volume 3A of the IA-32 Intel® Architecture Software Developer's Manual), in conjunction with a complex sequence of internal processor micro-architectural events, may lead to unexpected processor behavior.

**Implication:** This erratum may lead to livelock, shutdown or other unexpected processor behavior. Intel has not observed this erratum on any commercially available systems.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF53. SSE/SSE2 Streaming Store Resulting in a Self-Modifying Code (SMC) Event May Cause Unexpected Behavior**

**Problem:** An SSE or SSE2 streaming store that results in a Self-Modifying Code (SMC) event may cause unexpected behavior. The SMC event occurs on a full address match of code contained in L1 cache.

**Implication:** Due to this erratum, any of the following events may occur:  
1. A data access break point may be incorrectly reported on the instruction pointer (IP) just before the store instruction.

2. A non-cacheable store can appear twice on the external bus (the first time it will write only 8 bytes, the second time it will write the entire 16 bytes).

Intel has not observed this erratum with any commercially available software

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF54. Shutdown Condition May Disable Non-Bootstrap Processors**

**Problem:** When a logical processor encounters an error resulting in shutdown or VMX-Abort, non-bootstrap processors in the package may be unexpectedly disabled.

**Implication:** Non-bootstrap logical processors in the package that have not observed the error condition may be disabled and may not respond to INIT#, SMI#, NMI#, SIPI or other events

**Workaround:** When this erratum occurs, RESET# must be asserted to restore multi-core functionality.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF55. Split Locked Stores May not Trigger the Monitoring Hardware**

**Problem:** Logical processors normally resume program execution following the MWAIT, when another logical processor performs a write access to a WB cacheable address within the address range used to perform the MONITOR operation. Due to this erratum, a logical processor may not resume execution until the next targeted interrupt event or O/S timer tick following a locked store that spans across cache lines within the monitored address range.

**Implication:** The logical processor that executed the MWAIT instruction may not resume execution until the next targeted interrupt event or O/S timer tick in the case where the monitored address is written by a locked store which is split across cache lines.

**Workaround:** Do not use locked stores that span cache lines in the monitored address range.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF56. Writing Shared Unaligned Data that Crosses a Cache Line without Proper Semaphores or Barriers May Expose a Memory Ordering Issue**

**Problem:** Software which is written so that multiple agents can modify the same shared unaligned memory location at the same time may experience a memory ordering issue if multiple loads access this shared data shortly thereafter. Exposure to this problem requires the use of a data write which spans a cache line boundary.

**Implication:** This erratum may cause loads to be observed out of order. Intel has not observed this erratum with any commercially available software or system.

**Workaround:** Software should ensure at least one of the following is true when modifying shared data by multiple agents:

- The shared data is aligned
- Proper semaphores or barriers are used in order to prevent concurrent data accesses.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



**AF57. MSRs Actual Frequency Clock Count (IA32\_APERF) or Maximum Frequency Clock Count (IA32\_MPERF) May Contain Incorrect Data after a Machine Check Exception (MCE)**

**Problem:** When an MCE occurs during execution of a RDMSR instruction for MSRs Actual Frequency Clock Count (IA32\_APERF) or Maximum Frequency Clock Count (IA32\_MPERF), the current and subsequent RDMSR instructions for these MSRs may contain incorrect data.

**Implication:** After an MCE event, accesses to the IA32\_APERF and IA32\_MPERF MSRs may return incorrect data. A subsequent reset will clear this condition.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF58. An Enabled Debug Breakpoint or Single Step Trap May Be Taken after MOV SS/POP SS Instruction if it is Followed by an Instruction That Signals a Floating Point Exception**

**Problem:** A MOV SS/POP SS instruction should inhibit all interrupts including debug breakpoints until after execution of the following instruction. This is intended to allow the sequential execution of MOV SS/POP SS and MOV [r/e]SP, [r/e]BP instructions without having an invalid stack during interrupt handling. However, an enabled debug breakpoint or single step trap may be taken after MOV SS/POP SS if this instruction is followed by an instruction that signals a floating point exception rather than a MOV [r/e]SP, [r/e]BP instruction. This results in a debug exception being signaled on an unexpected instruction boundary since the MOV SS/POP SS and the following instruction should be executed atomically.

**Implication:** This can result in incorrect signaling of a debug exception and possibly a mismatched Stack Segment and Stack Pointer. If MOV SS/POP SS is not followed by a MOV [r/e]SP, [r/e]BP, there may be a mismatched Stack Segment and Stack Pointer on any exception. Intel has not observed this erratum with any commercially available software, or system.

**Workaround:** As recommended in the IA32 Intel® Architecture Software Developer's Manual, the use of MOV SS/POP SS in conjunction with MOV [r/e]SP, [r/e]BP will avoid the failure since the MOV [r/e]SP, [r/e]BP will not generate a floating point exception. Developers of debug tools should be aware of the potential incorrect debug event signaling created by this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**AF59. Incorrect Address Computed For Last Byte of FXSAVE/FXRSTOR Image Leads to Partial Memory Update**

**Problem:** A partial memory state save of the 512-byte FXSAVE image or a partial memory state restore of the FXRSTOR image may occur if a memory address exceeds the 64KB limit while the processor is operating in 16-bit mode or if a memory address exceeds the 4GB limit while the processor is operating in 32-bit mode.

**Implication:** FXSAVE/FXRSTOR will incur a #GP fault due to the memory limit violation as expected but the memory state may be only partially saved or restored.

**Workaround:** Software should avoid memory accesses that wrap around the respective 16-bit and 32-bit mode memory limits.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF60. Values for LBR/BTS/BTM will be Incorrect after an Exit from SMM**

**Problem:** After a return from SMM (System Management Mode), the CPU will incorrectly update the LBR (Last Branch Record) and the BTS (Branch Trace Store), hence rendering their data invalid. The corresponding data if sent out as a BTM on the system bus will also be incorrect.

Note: This issue would only occur when one of the three above mentioned debug support facilities are used.

**Implication:** The value of the LBR, BTS, and BTM immediately after an RSM operation should not be used.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF61. Using Memory Type Aliasing with Memory Types WB/WT May Lead to Unpredictable Behavior**

**Problem:** Memory type aliasing occurs when a single physical page is mapped to two or more different linear addresses, each with different memory type. Memory type aliasing with the memory types WB and WT may cause the processor to perform incorrect operations leading to unpredictable behavior.

**Implication:** Software that uses aliasing of WB and WT memory types may observe unpredictable behavior. Intel chipset-based platforms are not affected by this erratum.

**Workaround:** None identified. Intel does not support the use of WB and WT page memory type aliasing.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF62. Errata -- removed**

## **AF63. EFLAGS Discrepancy on a Page Fault After a Multiprocessor TLB Shutdown**

**Problem:** This erratum may occur when the processor executes one of the following read-modify-write arithmetic instructions and a page fault occurs during the store of the memory operand: ADD, AND, BTC, BTR, BTS, CMPXCHG, DEC, INC, NEG, NOT, OR, ROL/ROR, SAL/SAR/SHL/SHR, SHLD, SHRD, SUB, XOR, and XADD. In this case, the EFLAGS value pushed onto the stack of the page fault handler may reflect the status of the register after the instruction would have completed execution rather than before it. The following conditions are required for the store to generate a page fault and call the operating system page fault handler:

1. The store address entry must be evicted from the DTLB by speculative loads from other instructions that hit the same way of the DTLB before the store has completed. DTLB eviction requires at least three-load operations that have linear address bits 15:12 equal to each other and address bits 31:16 different from each other in close physical proximity to the arithmetic operation.
2. The page table entry for the store address must have its permissions tightened during the very small window of time between the DTLB eviction and execution of the store. Examples of page permission tightening include from Present to Not Present or from Read/Write to Read Only, etc.
3. Another processor, without corresponding synchronization and TLB flush, must cause the permission change.

**Implication:** This scenario may only occur on a multiprocessor platform running an operating system that performs “lazy” TLB shutdowns. The memory image of the EFLAGS register on the page fault handler’s stack prematurely contains the final arithmetic flag values although the instruction has not yet completed.



Intel has not identified any operating systems that inspect the arithmetic portion of the EFLAGS register during a page fault nor observed this erratum in laboratory testing of software applications.

**Workaround:** No workaround is needed upon normal restart of the instruction, since this erratum is transparent to the faulting code and results in correct instruction behavior. Operating systems may ensure that no processor is currently accessing a page that is scheduled to have its page permissions tightened or have a page fault handler that ignores any incorrect state.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF64. Returning to Real Mode from SMM with EFLAGS.VM Set May Result in Unpredictable System Behavior**

**Problem:** Returning back from SMM mode into real mode while EFLAGS.VM is set in SMRAM may result in unpredictable system behavior.

**Implication:** If SMM software changes the values of the EFLAGS.VM in SMRAM, it may result in unpredictable system behavior. Intel has not observed this behavior in commercially available software.

**Workaround:** SMM software should not change the value of EFLAGS.VM in SMRAM.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF65. Performance Monitoring Event FP\_ASSIST May Not be Accurate**

**Problem:** Performance monitoring event FP\_ASSIST (11H) may be inaccurate as assist events may be counted twice per actual assist in the following specific cases:

- FADD and FMUL instructions with a NaN (Not a Number) operand and a memory operand
- FDIV instruction with zero operand value in memory

In addition, an assist event may be counted when DAZ (Denormals-Are-Zeros) and FTZ (Flush-To-Zero) flags are turned on even though no actual assist occurs.

**Implication:** The counter value for the performance monitoring event FP\_ASSIST (11H) may be larger than expected. The size of the error is dependent on the number of occurrences of the above conditions while the event is active.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF66. The BS Flag in DR6 May be Set for Non-Single-Step #DB Exception**

**Problem:** DR6 BS (Single Step, bit 14) flag may be incorrectly set when the TF (Trap Flag, bit 8) of the EFLAGS Register is set, and a #DB (Debug Exception) occurs due to one of the following:

- DR7 GD (General Detect, bit 13) being bit set;
- INT1 instruction;
- Code breakpoint

**Implication:** The BS flag may be incorrectly set for non-single-step #DB exception.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF67. An Asynchronous MCE During a Far Transfer May Corrupt ESP**

**Problem:** If an asynchronous machine check occurs during an interrupt, call through gate, FAR RET or IRET and in the presence of certain internal conditions, ESP may be corrupted.

**Implication:** If the MCE (Machine Check Exception) handler is called without a stack switch, then a triple fault will occur due to the corrupted stack pointer, resulting in a processor shutdown. If the MCE is called with a stack switch, e.g. when the CPL (Current Privilege Level) was changed or when going through an interrupt task gate, then the corrupted ESP will be saved on the new stack or in the TSS (Task State Segment), and will not be used.

**Workaround:** Use an interrupt task gate for the machine check handler.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF68. BTM/BTS Branch-From Instruction Address May be Incorrect for Software Interrupts**

**Problem:** When BTM (Branch Trace Message) or BTS (Branch Trace Store) is enabled, a software interrupt may result in the overwriting of BTM/BTS branch-from instruction address by the LBR (Last Branch Record) branch-from instruction address.

**Implication:** A BTM/BTS branch-from instruction address may get corrupted for software interrupts.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

## **AF69. Store to WT Memory Data May be Seen in Wrong Order by Two Subsequent Loads**

**Problem:** When data of Store to WT memory is used by two subsequent loads of one thread and another thread performs cacheable write to the same address the first load may get the data from external memory or L2 written by another core, while the second load will get the data straight from the WT Store.

**Implication:** Software that uses WB to WT memory aliasing may violate proper store ordering.

**Workaround:** Do not use WB to WT aliasing.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



#### **AF70. Single Step Interrupts with Floating Point Exception Pending May Be Mishandled**

**Problem:** In certain circumstances, when a floating point exception (#MF) is pending during single-step execution, processing of the single-step debug exception (#DB) may be mishandled.

**Implication:** When this erratum occurs, #DB will be incorrectly handled as follows:

- #DB is signaled before the pending higher priority #MF (Interrupt 16)
- #DB is generated twice on the same instruction

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#)

#### **AF71. Non-Temporal Data Store May be Observed in Wrong Program Order**

**Problem:** When non-temporal data is accessed by multiple read operations in one thread while another thread performs a cacheable write operation to the same address, the data stored may be observed in wrong program order (i.e. later load operations may read older data).

**Implication:** Software that uses non-temporal data without proper serialization before accessing the non-temporal data may observe data in wrong program order.

**Workaround:** Software that conforms to the *Intel® 64 and IA-32 Architectures Software Developer's Manual*, Volume 3A, section “Buffering of Write Combining Memory Locations” will operate correctly.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF72. Fault on ENTER Instruction May Result in Unexpected Values on Stack Frame**

**Problem:** The ENTER instruction is used to create a procedure stack frame. Due to this erratum, if execution of the ENTER instruction results in a fault, the dynamic storage area of the resultant stack frame may contain unexpected values (i.e. residual stack data as a result of processing the fault).

**Implication:** Data in the created stack frame may be altered following a fault on the ENTER instruction. Please refer to "Procedure Calls For Block-Structured Languages" in IA-32 Intel® Architecture Software Developer's Manual, Vol. 1, Basic Architecture, for information on the usage of the ENTER instructions. This erratum is not expected to occur in ring 3. Faults are usually processed in ring 0 and stack switch occurs when transferring to ring 0. Intel has not observed this erratum on any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF73. Unaligned Accesses to Paging Structures may Cause the Processor to Hang**

**Problem:** When an unaligned access is performed on paging structure entries, accessing a portion of two different entries simultaneously, the processor may live lock.

**Implication:** When this erratum occurs, the processor may live lock causing a system hang.

**Workaround:** Do not perform unaligned accesses on paging structure entries.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



#### **AF74. Microcode Updates Performed During VMX Non-root Operation Could Result in Unexpected Behavior**

**Problem:** When Intel® Virtualization Technology is enabled, microcode updates are allowed only during VMX root operations. Attempts to apply microcode updates while in VMX non-root operation should be silently ignored. Due to this erratum, the processor may allow microcode updates during VMX non-root operations if not explicitly prevented by the host software.

**Implication:** Microcode updates performed in non-root operation may result in unexpected system behavior.

**Workaround:** Host software should intercept and prevent loads to IA32\_BIOS\_UPDT\_TRIG MSR (79H) during VMX non-root operations. There are two mechanism that can be used (1) Enabling MSR access protection in the VM-execution controls or (2) Enabling selective MSR protection of IA32\_BIOS\_UPDT\_TRIG MSR.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF75. INVLPG Operation for Large (2M/4M) Pages may be Incomplete under Certain Conditions**

**Problem:** The INVLPG instruction may not completely invalidate Translation Look-aside Buffer (TLB) entries for large pages (2M/4M) when both of the following conditions exist:

- Address range of the page being invalidated spans several Memory Type Range Registers (MTRRs) with different memory types specified
- INVLPG operation is preceded by a Page Assist Event (Page Fault (#PF) or an access that results in either A or D bits being set in a Page Table Entry (PTE))

**Implication:** Stale translations may remain valid in TLB after a PTE update resulting in unpredictable system behavior. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software should ensure that the memory type specified in the MTRRs is the same for the entire address range of the large page.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF76. Page Access Bit May be Set Prior to Signaling a Code Segment Limit Fault**

**Problem:** If code segment limit is set close to the end of a code page, then due to this erratum the memory page Access bit (A bit) may be set for the subsequent page prior to general protection fault on code segment limit.

**Implication:** When this erratum occurs, a non-accessed page which is present in memory and follows a page that contains the code segment limit may be tagged as accessed.

**Workaround:** Erratum can be avoided by placing a guard page (non-present or non-executable page) as the last page of the segment or after the page that includes the code segment limit.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF77. Performance Monitoring Events for Hardware Prefetch Requests (4EH) and Hardware Prefetch Request Cache Misses (4FH) May Not be Accurate**

**Problem:** Performance monitoring events that count hardware prefetch requests and prefetch misses may not be accurate.





**Implication:** This erratum may cause inaccurate counting for Hardware Prefetch Requests and Hardware Prefetch Request Cache Misses.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF78. EFLAGS, CR0, CR4 and the EXF4 Signal May be Incorrect after Shutdown**

**Problem:** When the processor is going into shutdown due to an RSM inconsistency failure, EFLAGS, CR0 and CR4 may be incorrect. In addition the EXF4 signal may still be asserted. This may be observed if the processor is taken out of shutdown by NMI#.

**Implication:** A processor that has been taken out of shutdown may have an incorrect EFLAGS, CR0 and CR4. In addition the EXF4 signal may still be asserted.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **AF79. Store Ordering May be Incorrect between WC and WP Memory Types**

**Problem:** According to Intel® 64 and IA-32 Intel Architecture Software Developer's Manual, Volume 3A "Methods of Caching Available", WP (Write Protected) stores should drain the WC (Write Combining) buffers in the same way as UC (Uncacheable) memory type stores do. Due to this erratum, WP stores may not drain the WC buffers.

**Implication:** Memory ordering may be violated between WC and WP stores.

**Workaround:** None identified.

**Status:** For the affected steppings, see the [Summary Tables of Changes](#).

#### **AF80. A WB Store Following a REP STOS/MOVS or FXSAVE May Lead to Memory-Ordering Violations**

**Problem:** Under certain conditions, as described in the Software Developers Manual section "Out-of-Order Stores For String Operations in Pentium 4, Intel Xeon, and P6 Family Processors", the processor may perform REP MOVS or REP STOS as write combining stores (referred to as "fast strings") for optimal performance. FXSAVE may also be internally implemented using write combining stores. Due to this erratum, stores of a WB (write back) memory type to a cache line previously written by a preceding fast string/FXSAVE instruction may be observed before string/FXSAVE stores.

**Implication:** A write-back store may be observed before a previous string or FXSAVE related store. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software desiring strict ordering of string/FXSAVE operations relative to subsequent write-back stores should add an MFENCE or SFENCE instruction between the string/FXSAVE operation and following store-order sensitive code such as that used for synchronization.

**Status:** For the affected steppings, see the [Summary Tables of Changes](#).

## Specification Changes

---

There are no specification changes in this specification update revision.

**Note:** All specification changes will be incorporated into a future version of the appropriate processor documentation.

§



# Specification Clarifications

---

## 1. Enhanced Cache Error Reporting for D0 Stepping

Beginning with the D0 stepping, enhanced cache error reporting - as described in Section 14.4 of the *Intel® 64 and IA-32 Architectures Software Developer's Manual (SDM), Volume 3A: System Programming Guide* – is supported by the processor. Older steppings use the original cache error reporting scheme. Please see the SDM, Volume 3A, for more details.

**Note:** All specification clarifications will be incorporated into a future version of the appropriate processor documentation.

§

## Documentation Changes

---

There are no documentation changes in this specification update revision.

**Note:** All document changes will be incorporated into a future version of the processor documentation.

**Note:** Documentation changes for Intel® 64 and IA-32 Architectures Software Developer Manual volumes 1, 2A, 2B, 3A, and 3B will be posted in a separate document named *Intel® 64 and IA-32 Architectures Software Developer's Manual Documentation Changes*. Follow the link below to become familiar with this file.

<http://developer.intel.com/design/pentium4/specupdt/252046.htm>